




Fire Risk Assessment

Risk Assessment – Record of significant findings		
Risk assessment for:	Carpark Barn @ Walton firs	Assessment undertaken by: Robert Williams- Operations Manager Qualifications: Health & Safety Compliance Instructor

Step 1 – Identify fire hazards		
Sources of ignition: Power supplies, Naked Flames, Overloading power.	Sources of Fuel: Timber, Plastics, Chemicals, Fabrics, Camping/Activity equipment.	Sources of Oxygen: Atmosphere

Step 2 – People at Risk
Site Staff, Visitors and Campers.

Step 3 – Evaluate, Remove, Reduce and protect from risk	
(3.1) Evaluate the risk of the fire occurring.	Low Risk for all unless, campers or Visitors bring other sources of ignition. I.e. fires campfires, BBQ's or Cooking equipment.
(3.2) Evaluate the Risk to people from a fire starting on the premises.	Low risk to site staff campers and visitors as it has open sides for exiting, and to move clear from. It is a small single storey building. Medium risk as it is located next to a carpark.
(3.3) Remove and reduce the hazards that may cause a fire.	Policies in place to keep naked flames out of the building no exceptions. It is clear no smoking and cooking in or near the building.
(3.4) Remove and Reduce the risks to people from a fire.	Training of use of equipment, following operational policies and procedures. The electrics supply covered by multiple RCD safety breakers.

Assessment Review		
Assessment/Review date: 04/2020	Completed by: Robert Williams	Signature: 
Review outcome (where substantial changes have occurred a new record sheet should be used)		